DEPARTMENT OF TRANSPORTATION

District 11 – Materials Engineering 7177 Opportunity Rd. San Diego, CA 92111



CALTRANS QUALIFIED LABORATORY INSPECTION REPORT

Expiration date: July 25, 2013.

Inspection by: Roy E Denner Jr

IA No.: 049

Phone: 858-467-4067

File: Materials Category 500

Laboratory: Clarkson Laboratory and Supply, Inc.

Address: 350 Trousdale Dr.

City: Chula Vista State: CA Zip: 91910

Lab Manager: Sheley De Wall E-mail: laura@clarksonlab.com

Phone #: 619-425-1993 Fax #: 619-425-7917

A certified Independent Assurance (IA) Sampler and Tester visited this laboratory on July 25, 2012. Only equipment to be used on Caltrans construction projects and/or local construction projects on the National Highway System projects was checked for qualification.

At the time of Caltrans Qualification, this laboratory had all necessary equipment to perform the tests methods indicated below. Testing personnel shall be Caltrans Qualified and possess a current Caltrans Certificate of Proficiency Form TL-0111 prior to performing any sampling or testing.

CT417 CT422 CT643

A visual check was performed and documents provided as necessary for the following items:

Kacility Safety Manual

Laboratory Procedures Manual

Laboratory Quality Control Manual

Proper Test Equipment

Copies of current applicable test procedures

Calibration and Service Documentation

Calibration/Service stickers affixed to test equipment

Laboratory Qualification is valid for one year

On July 25, 2012 this laboratory was qualified by:

Roy E Denner Jr

District 11, Independent Assurance